



SPECIFICATION AMENDMENTS:

Please amend paragraph [0122] as follows:

Further, in the case that the motor is connected inside the vehicle body-side tube, since key components of the electromagnetic shock absorber for the vehicle such as the motor, ball screw nut, and screw shaft are covered by the axle-side tube and the vehicle body-side tube. ~~Therefore,~~ therefore, when applied to a vehicle, damage ~~[[of]]~~ to the electromagnetic shock absorber for the vehicle due to the rain, mud stones or the like can be effectively prevented.